

TRUMBULL

1040 N. Meridian Rd., P.O. Box 1556, Youngstown, Ohio 44501
 Phone: 330.799.3333 • Toll Free: 800.677.1799 • FAX: 330.797.3215

www.trumbull-mfg.com

CURB BOX REPAIR LIDS

When you have any of these problems...



Lost Lid



Broken Lug



Broken Top


...use Trumbull Curb Box Repair Lids to solve the problem of lost lids, broken lugs or broken tops on 2-1/2" and 3" Buffalo style curb boxes!



Inside (New Style)



Inside (New Style)
T-373



Installation of T-373



Outside (Old Style)



Outside (Old Style)
T-374 (2-1/2") & T-375 (3")



Installation
of T-374, T-375

All 3 styles of **CURB BOX REPAIR LIDS** feature a brass screw, assembled after painting, to facilitate operation. To install, insert the two jaws into the shaft and tighten the screw with a standard pentagon key. The jaws expand to bear against the inside of the curb box. Designed to fit most makes of curb boxes, both old and new. Outside Repair Lids also work on most makes of inside style Curb Boxes; however, inside Repair Lids only work on inside style Curb Boxes.

<u>Trumbull Item No.</u>	<u>Model No.</u>	<u>Description</u>	<u>Weight</u>
367-4281	T-373	2-1/2" Inside (New Style)	2.25 lbs.
367-4282	T-374	2-1/2" Outside (Old Style)	2.25 lbs.
367-4283	T-375	3" Outside	3.50 lbs.